



Building Inspection Report

Unit 502

Sunset Towers





Unit 502

Following inspection and re-inspection, the identified defects within the agreed inspection scope have been reviewed. The previously reported items have been satisfactorily rectified, except for any items listed as outstanding in the accompanying report. This certificate records the condition of the inspected works at the time of inspection.





QUALITY ASSURANCE CERTIFICATE

GoInspect Pty Ltd has inspected:

Unit 502

*At:
“Sunset Towers”
39 Sunset Street
West End, Queensland*

*This unit meets and exceeds industry standard.
Authorised:*

Daniel Jurekie

*Daniel Jurekie
Director, GoInspect Pty Ltd*

Date issued:
17 June, 2026



Outstanding Defects

Defect ID	Area	Importance	Description
4273	Bathroom	Medium	Silicone incomplete to shower frame
4289	Bathroom	Medium	Second coat of paint required to Access Panel
4291	Ensuite	Medium	Patch and paint around extraction fan