

#747 | Balcony | Installer

Install clothesline



#749 | Balcony | Tiler

Remove partially grouted control joint in corner and silicone



#715 | Bathroom | Cabinet Maker

Fit bottom vanity drawer in track



#716 | Bathroom | Mirrors, Screens & Robes

Remove packer below shower screen and silicone



#732 | Bed 1 | Silicone Installer

Silicone below skirting in robe



#733 | Bed 1 | Cabinet Maker

Install robe hanging rail centre support



#738 | Bed 2 | Cabinet Maker

Touch up chips on shelf support panel



#744 | Bed 3 | Cabinet Maker

Install robe hanging rail centre support



#701 General Plumber Water turned off at time of inspection	#752 General Tiler Point missing and inconsistent grout to tiles where required 
#711 Hallway Tiler Rectify chipped tile in front of linen cupboard 	#704 Kitchen Tiler Rectify chipped tile in front of fridge space 
#705 Kitchen Plumber Dishwasher legs are not stable 	#707 Kitchen Cabinet Maker Fit screw covers in rangehood overhead cabinet 
#708 Kitchen Silicone Installer Remove grout & improve silicone on left of splashback 	#710 Kitchen Cabinet Maker Fit shelf below hotplate 

#723 | Laundry | Plumber

Washing machine hose cock flanges are loose



#724 | Laundry | Silicone Installer

Rectify untooled silicone right of laundry splashback



#726 | Laundry | Plumber

Laundry tub spout is loose in wall



#727 | Laundry | Tiler

Rectify hole in tiles behind laundry spout



#729 | Laundry | Silicone Installer

Improve silicone in corner above laundry tub



#751 | Meals/Family | Tiler

Rectify chipped tile below A/C unit



#721 | Powder room | Carpenter

Toilet roll holder is loose



#753 | Powder room | Cabinet Maker

Rectify chipped laminate in corner of vanity

